


• SODERBERG AND GOODMAN LINES



Lecture Machine Design

- Gerber Line A parabolic curve joining S_e on the ordinate to S_{ut} on the abscissa is called the Gerber line.
- Soderberg Line A straight line joining S_e on the ordinate to S_{yt} on the abscissa is called the Soderberg line.
- Goodman Line A straight line joining S_e on the ordinate to S_{ut} on the abscissa is called the Goodman line.

We will apply following form for the equation of a straight line,

$$\frac{x}{a} + \frac{y}{b} = 1$$

where a and b are the intercepts of the line on the X and Y axes respectively.

Applying the above formula, the equation of the Soderberg line is given by,

$$\frac{\sigma_m}{S_{yt}} + \frac{\sigma_a}{S_e} = 1 \quad (5.36)$$

Similarly, the equation of the Goodman line is given by,

$$\frac{\sigma_m}{S} + \frac{\sigma_a}{S} = 1 \quad (5.37)$$

The Goodman line is widely used as the criterion of fatigue failure when the component is subjected to mean stress as well as stress amplitude. It is because of the following reasons:

- (i) The Goodman line is safe from design considerations because it is completely inside the failure points of test data.
- (ii) The equation of a straight line is simple compared with the equation of a parabolic curve.
- (iii) It is not necessary to construct a scale diagram and a rough sketch is enough to construct fatigue diagram.

- MODIFIED GOODMAN DIAGRAMS




Fig. 5.40 Modified Goodman Diagram for Axial and Bending Stresses





Fig. 5.41 Modified Goodman Diagram for Torsional Shear Stresses



Lecture Machine Design

- The components, which are subjected to fluctuating stresses, are designed by constructing the modified Goodman diagram. For the purpose of design, the problems are classified into two groups:
 - (i) components subjected to fluctuating axial or bending stresses; and
 - (ii) components subjected to fluctuating torsional shear stresses. While solving a problem, a line OE with a slope of $\tan \theta$ is constructed in such a way that,

$$\tan \theta = \frac{\sigma_a}{\sigma_m} \quad (5.38)$$

Since $\frac{\sigma_a}{\sigma_m} = \frac{(P_a / A)}{(P_m / A)} = \frac{P_a}{P_m}$

$$\therefore \tan \theta = \frac{P_a}{P_m} \quad (5.39)$$

The magnitudes of P_a and P_m can be determined from maximum and minimum forces acting on the component.

Similarly, it can be proved that

$$\tan \theta = \frac{(M_b)_a}{(M_b)_m} \quad (5.40)$$

The magnitudes of $(M_b)_a$ and $(M_b)_m$ can be determined from maximum and minimum bending moment acting on the component.

The point of intersection of lines AB and OE is X.

The point X indicates the dividing line between the safe region and the region of failure. The coordinates of the point X (S_m , S_a) represent the limiting values of stresses, which are used to calculate the dimensions of the component. The permissible stresses are as follows:

$$\sigma_a = \frac{S_a}{(fs)} \quad \text{and} \quad \sigma_m = \frac{S_m}{(fs)} \quad (5.41)$$

The modified Goodman diagram for fluctuating torsional shear stresses is shown in Fig. 5.41. In this diagram, the torsional mean stress is plotted on the abscissa while the torsional stress amplitude on the ordinate. The torsional yield strength S_{sy} is plotted on the abscissa and the yield line is constructed, which is inclined at 45° to the abscissa. The point of intersection of this line and the yield line is B. The area OABC represents the region of safety in this case. It is not necessary to construct a fatigue diagram for fluctuating torsional shear stresses because AB is parallel to the X-axis. Instead, a fatigue failure is indicated if,

$$\tau_a = S_{se} \quad (5.42)$$

and a static failure is indicated if,

$$\tau_{\max} = \tau_a + \tau_m = S_{sy} \quad (5.43)$$

The permissible stresses are as follows:

$$\tau_a = \frac{S_{se}}{(fs)} \quad (5.44)$$

and

$$\tau_{\max} = \frac{S_{sy}}{(fs)} \quad (5.45)$$